

9/19/2017 4T1CA30P64U010972

097204

TOYOTA 2004 CAMRY SOLA Color SILVER

Mileage 229530 or exceeded Initials \_\_\_\_\_ Location \_\_\_\_\_ StartsDONT NEED  
PICTURESDoors (2)3 4 Cond: LF Excellent Good (Poor) No Good  
LR Excellent Good Poor No GoodElectric windows (LF RF) Electric Trunk Cable Trunk release

RF RR Power Locks Power Seats Title filed Yes NO

Mirror Left Manual Cable (Elec) Excellent Good Poor (No Good)Wheels Alloy How Many 4 Steel Lugs 5 Size 16Tires Number 4 Excellent Good (Poor) No Good Size \_\_\_\_\_Antenna Manual (Electric) (Radio) (CD) (Ignition Key) Door KeyPROCESS  
FOR  
PARTSInterior Excellent Good (Poor) No Good Interior color Grey  
Glass 7Transmission (Automatic) Overdrive 4x4 Front Wheel Drive

Manual Three speed Four Speed Five Speed Six Speed

Steering Column Tilt Excellent Good (Poor) No Good(Cruise on Turn signal) Cruise on Str Wheel No Cruise Air Bag (Good LR)Fender Left Excellent Good (Poor) No GoodHood Excellent Good (Poor) No GoodAir cond compressor (Y) Cond. Excellent (Good) Poor No Good UnkEngine size/type V6 3.3 MFI EFI Turbo TBI Carburetor DieselHeadlights :L Excellent (Good) Poor No Good Wiper MotorR Excellent (Good) (Poor) No GoodTurn Lens: L. Excellent (Good) (Poor) No GoodR. Excellent (Good) (Poor) No GoodBumper Front Excellent Good Poor (No Good)Grill Excellent Good Poor (No Good)Fender Right Excellent Good (Poor) No Good(Alternator) (Battery) (Radiator) Ladder Rack Spare Tire DonutDoors Right RF Excellent Good (Poor) No Good

RR Excellent Good Poor No Good

Hatch Back Yes \_\_\_\_\_ Excellent Good Poor No Good

Mirror Right Manual Cable (Elec) Excellent (Good) (Poor) No Good

PROCESSOR

Battery removed X Gas tank removed X Fluids drained X(Trunk) bed or hatch condition Excellent Good Poor No GoodBumper Rear condition Excellent Good Poor (No Good)Taillights L Excellent Good (Poor) No GoodR Excellent (Good) Poor No Good Rear Wiper Good1 Piece Excellent (Good) Poor No Good