

Vehicle Detail

Loss Type: COLLISION

Year: 1996 Damage: FRONT & REAR

Make: CHEVROLET Start: WON'T START

Model: CAMARO Key: NO

Cert. State: Ohio Odometer: 118693

**Sale Document: SALVAGE Odom. Status:
ACTUAL**

Sale Document

Brand:

VIN: 2G1FP22K3T2161194

Sale Document

Notes:

Additional Vehicle Information

Body Style: COUPE CD Player: YES

**Color: GREEN Engine Size: 3.8L V6 MPI OHV
12V NM2**

Air Bags: 4 Radio: YES

ACV: \$4,135.00 Driver Airbag: DEPLOYED

Passenger Airbag: DEPLOYED Left Side

Airbag: NONE

Right Side Airbag: NONE VIN Status: OK